


Salt20 Pocket Salinity Tester

Instruction Manual






APERA INSTRUMENTS, LLC <u>www.aperainst.com</u>

Salt20 Pocket Salinity Tester Instruction Manual

1. Battery Installation

Please install batteries according to the following steps. Please note polarity:

"+" (anode) is upward; "-" (cathode) is downward



2. Keypad Functions

Short press------ < 2 seconds

■ Long press------> 2 seconds

| | | | 1 |
|----------------|--|------------------------------|-----|
| | 1. Short press to turn on, long press to turn off; | | LCD |
| (\bigcirc) | 2. When turned off, long press to enter setup; | <u>נט</u> פון איז פון איז | 1 |
| MEAS | 3. In mode setting, short press to change | | Ke |
| | parameter; | | |
| | 1. When turned on, long press to enter | ANTEROMOST | |
| | calibration mode. | | |
| (<u>-</u>) | 2. In calibration mode, short press to confirm | | pH |
| | calibration; | <u>FILL</u> | Pro |
| | 3. In mode setting, short press to confirm | LAN F | |
| | parameter selection. | | |




Diagram - 1

3. Complete Kit




Diagram - 2

4. Calibration

4.1 Rinse the probe in distilled water and dry it. Short press (1) (MEAS) to turn on the tester.
4.2 Long press (CAL / CH) to enter calibration mode; Short press (1) (MEAS) to exit. Diagram - 3
4.3 Dip the probe into 5 ppt calibration solution. Stir gently, leave it to stand,
LCD displays (2) (Diagram 3), short press (CAL / CH) to complete 1-point calibration.
The tester returns to measuring mode, and calibration icon (H) appears at the button left of LCD.

5. Salinity Measurement

5.1 Short press (U) to turn on tester. Rinse probe in distilled water and dry it.
5.2 Stir probe in the sample solution gently, leave it to stand. Get readings after the smile icon comes up and stays.

6. Notes

6.1 The tester has self-diagnosis functions:

| Symbol | Self-Diagnosis information | How to fix | |
|--------|---|--|--|
| Er I | Wrong calibration solution, which exceeds the recognizable range of the meter. | Check if calibration solution is correct Check if probe is damaged. | |
| Er2 | (CAL) is pushed before measurement is stable (CO) comes up) | Wait for the smile icon to stay and then short press (| |

6.2 The tester has already been calibrated after manufacture. Usually users can use the tester right away, or test it in the calibration solutions to test its accuracy. When error is large, calibrate it before using.

7. Parameter Setting

7.1 Parameter setting reference chart:

| Symbol | Parameter Setting content | Code | Factory Default |
|--------|----------------------------|------------|-----------------|
| P1 | Select salinity unit | ppt – mg/L | ppt |
| P2 | Restore to factory default | No – Yes | No |

7.2 How to setup parameters:

When turned off, long press $\underbrace{\begin{pmatrix} \bigcup \\ MEAS \end{pmatrix}}_{MEAS}$ to enter setup \rightarrow short press $\underbrace{\begin{pmatrix} \bigcup \\ MEAS \end{pmatrix}}_{MEAS}$ to switch P1-P2 \rightarrow Short press $\underbrace{\begin{pmatrix} \square \\ \square \end{pmatrix}}_{MEAS}$, parameter flickering \rightarrow short press $\underbrace{\begin{pmatrix} \bigcup \\ MEAS \end{pmatrix}}_{MEAS}$ to choose, short press $\underbrace{\begin{pmatrix} \square \\ \square \end{pmatrix}}_{MEAS}$ to confirm parameter selection \rightarrow Long press $\underbrace{\begin{pmatrix} \bigcup \\ MEAS \end{pmatrix}}_{MEAS}$ to switch off. 7.3 Parameter setting notes

a) Select salinity unit(P1):

Optional units: ppt - mg/L, factory default is ppt.

b) Restore to factory default:

Select Yes to restore the calibration to the theoretical values and parameter setting to original values. When meter's calibration or measurement performs abnormally, this function can be adopted so the meter goes back to factory default setting and then users can conduct calibration or take measurements again.

8. Technical Specifications

| Salinity | Range | 0 - 10.00 ppt | |
|----------|--------------------|--------------------------|--|
| | Resolution | 0.01 ppt | |
| | Accuracy | ±1% F.S | |
| | Calibration points | 1 point auto calibration | |
| | Automatic Temp. | 0-50 [°] C | |
| | Compensation | | |
| Temp. | Range | 0-50 [°] C | |
| | Resolution | 0.1 [°] C | |
| | Accuracy | ±0.5°C | |

9. Other Functions & Parameters

| Indication of calibration points | H | Auto Power- off | Power-off in 8 minutes if no operation |
|-----------------------------------|--|---------------------|--|
| Indication of stable measurements | 0 | Waterproof level | IP67, floats on water |
| Self-Diagnosis information | Er1, Er2 | Power Supply | AAA batteries*4 |
| Low battery reminder | Flashes to remind to replace batteries | Battery Life | 1000 hours |
| Dimensions/Weight | Instrument: 40*31*178mm/107g; Carrying case: 190*165*140mm/438g | | |

10. Warranty

We warrant this instrument to be free from defects in material and workmanship and agrees to repair or replace free of charge, at option of APERA INSTRUMENTS, LLC, any malfunctioned or damaged product attributable to responsibility of APERA INSTRUMENTS, LLC for a period of **two years** from the delivery (a **six-month** limited warranty applies to probes). This warranty does not apply to defects resulting from actions such as misuse (violation of the instructions in this manual or operations in the manner not specified in this manual), improper maintenance, and unauthorized repairs. Warranty period is the time limit to provide free service for the products purchased by customers, not the service life of the tester or probe.

Apera Instruments reserves the right to update the information in this manual without giving notice in advance.

APERA INSTRUMENTS, LLC

Address: 977 Old Henderson Rd, Columbus Ohio 43220

Tel: 1-614-285-3080

Email: info@aperainst.com

Website: www.aperainst.com