



DTH04 USER'S MANUAL



Jumbo Display Thermo-Hygrometer with Clock

THERMOMETER OPERATION

On/Off:

1. Press ON/OFF button once to switch on the thermometer and press again to switch it off.
2. "WARM", "COMFORT" or "COOL" sign appears at appropriate temperature and humidity.

°C/°F:

1. Press °C/°F button to select desirable temperature unit.

Max/Min:

1. Press MAX/MIN button once to recall maximum temperature and humidity tested. MAX sign will appear on the display.
2. Press button again to recall minimum temperature and humidity tested. MIN sign will appear on the display.
3. Unit restores to real time mode automatically after 5 seconds.

Time Set:

1. Press TIME SET button for 3 seconds. Digit at the lowest display blinking means clock is in set mode.
2. Press HR and MIN buttons respectively to adjust the desired time.
3. Press 12/24 to select time format.
4. Press TIME SET button to return to real time mode. Or unit returns to real time mode automatically in 5 seconds.

In/Out:

1. Press IN/OUT button once to display outdoor measurement. OUT sign will appear on the display.
2. Press button again to display indoor measurement. IN sign will appear on the display.

Alarm Set:

1. Press AL/SNZ button for 3 seconds to alarm set mode. AL sign appear on the display.
2. Press HR and MIN buttons to adjust to the desired alarm time.
3. Press TIME SET button again after setting and the unit will return to real time mode automatically after 3 seconds.

Snooze Set:

1. After alarm set, press AL/SNZ button to activate the alarm and snooze function. and SNZ signs will appear on the LCD.
2. After setting, the unit will automatically return to real time mode in 3 seconds.
3. When the set alarm time is reached, the alarm sign flashes and the alarm will last for 1 minute or press any key to stop it.
4. The snooze will sound 10 minutes after the set alarm time for 5 times. When the snooze reaches, SNZ sign will flash.
5. To clear the snooze function, press AL/SNZ for 3 seconds to enter the alarm set mode first. Then press AL/SNZ once again. and SNZ signs will disappear.



Specialty Tools & Instruments™

GENERAL TOOLS & INSTRUMENTS™

80 White Street
New York, NY 10013-3567
PHONE (212) 431-6100
FAX (212) 431-6499
TOLL FREE (800) 697-8665

e-mail: sales@generaltools.com
www.generaltools.com
DTH04 User's Manual

Specifications subject to change
without notice.

©2009 GENERAL TOOLS & INSTRUMENTS™
NOTICE - WE ARE NOT RESPONSIBLE FOR TYPOGRAPHICAL ERRORS.
MANHDTH04 03/09