



FLIR TA7x UNIVERSAL FLEX CURRENT PROBE ACCESSORIES

VFD APPLICATION INCOMPATIBILITY

Models TA72 and TA74 are not designed for use with VFD (Variable Frequency Drive) equipment, as erroneous readings may result.

Note that testing with VFD equipment does not pose a safety hazard to personnel and will not damage equipment.

Please contact FLIR for additional information.

To view this document in other languages, please visit: <http://support.flir.com>

Corporate Headquarters

FLIR Systems, Inc.
2770 SW Parkway Avenue
Wilsonville, OR 97070
USA

Customer Support

| | |
|----------------------------|---|
| Technical Support Website | http://support.flir.com |
| Technical Support Email | TMSupport@flir.com |
| Service and Repair Email | Repair@flir.com |
| Customer Support Telephone | +1 855-499-3662 (toll free) |

© Copyright 2015, FLIR Systems, Inc. All rights reserved worldwide

