

INSTRUCTIONS FOR A600FC

Description

This is a meter which has Thermometer/Humidity on one dial, it can be applied widely, in all stainless steel construction, it can provide temperature and humidity indication.

room, warehouse, workshop

Areas of Application Air-condition

room, laboratory, computer room, sauna nursery, office and bedroom.

Working Condition

1. Indoor Application, static state, no wind flows. 2. NO shaking on the hanging position

Technical Data

Accuracy-

Temperature: +/-2F

Humidity:+/-6%

Range -Temperature: 30/250F&C Dual Scales

Humidity: 0/100%

Notice for using and maintenance

- 1. The hanging position is not available if the wall with sunshine beating and vent hole of air-condition machine (bad air-flowing state). It can have correct indicating after 30 minutes.
- 2. It can't be poured by rain, and put in the surrounding which has corrodible gas to brass.
- 3. If in doubt to the indicating, put the meter in a small room without any wind flowing, 30 minutes later, adjust on the back to get the accurate indication according to the standard instrument.