

# DIGITAL POCKET THERMOMETER


## Specifications :

Accuracy :	$\pm 1^{\circ}\text{C} / \pm 2^{\circ}\text{F}$ between $-4 - 248^{\circ}\text{F}$ $-20 - 120^{\circ}\text{C}$ otherwise $\pm 2^{\circ}\text{C} \pm 4^{\circ}\text{F}$
Resolution :	$0.1^{\circ}$ between $-19.9 - 199.9^{\circ}$ otherwise $1^{\circ}$
Sampling time :	1 second
Battery :	1.5 Volt x 1
Battery life :	5000 hours
Ambient temperature :	$-10 - 50^{\circ}\text{C}$ or $14 - 122^{\circ}\text{F}$
Automatic power off after 10 mins.	

## Operation :

1. Take off the probe cover.
2. Press [ON/OFF] to switch on.
3. Insert probe into test substance about 50 mm (2").
4. Get the reading when it is steady.
5. Press [C/F] to choose temperature unit.
6. Press [ON/OFF] again to switch off.

## Battery Replacement :



- Flip up the battery compartment on the bottom cabinet.
- Turn left to open the battery cover for new battery replacement.
- Turn right to close the battery cover.