

INSTALLATION INSTRUCTIONS FOR L-900 OUTLET BOX PLATE

For use with L610, L620, L640 & L-650 Series Track system ONLY.

1. Position plate over outlet box and locate mounting screw hole position on plate and mark exact location in plastic coating. With a sharp tool, pierce the plastic coating in the exact position of mounting screws. If mounting holes are in a knock-out location, knock-outs should be removed only by punching thru the mounting hole location. This will insure a neat looking installation without extra holes.
2. Position respective connector (live-end, "L", "T", "X") over plate to select proper hole(s) for screw(s) provided in back plate of connector. Pierce plastic coating with tool to start screw.



Pre-punched, "Universal" design with plastic coating on exposed side, can be painted with oil or latex base paints.

CATALOG NO:	FINISH
L-900	MB

HALO LIGHTING
400 BUSSE ROAD
ELK GROVE VILLAGE, IL 60007

696380
606380