

## 994 Sloped Ceiling Pendant Trac Adapter

(Converts straight hanging pendant kits #L992 or L993 to swivel hanging pendant for sloped ceilings.)

**Step 1.** Discard 5" canopy and 5" diameter stem mtg. plate (if it is not being used as a splice plate in a "T" bar ceiling) from L992 or L993 pendant kits and substitute with parts in L994 45° pendant trac adapter.

**Step 2.** Assemble mounting strap to outlet box screws or splice plate in a "T" bar ceiling.

**Step 3.** Assemble swivel ball with (2) set screws (allen wrench provided) to end of 18" stem.

**o 4.** Slide ball end through mounting strap slot and mount canopy to mounting strap with (2) screws, as shown.

**Step 5.** For converting #L992 only. Slide pendant bracket cover over stem as shown.

**Step 6.** Assemble (2) 1/4-28 hex nuts to stem end with approximately 3/8" between the nuts.

**Step 7.** Assemble pendant bracket to mini trac with #10-24 nut and screw. If Raceway trac, slide pendant bracket on to trac for assembly, and use screws to position.

**Step 8.** Raise trac with assembled pendant brackets and slide between the 1/4-28 nut on stem end and into slot on pendant bracket.

**Step 9.** Tighten nuts to secure.

