



PS500

Quick Operation Guide



Switch On



Switch Off



OFF 3





OFF 2

OFF 1

Backlight On

Max

Min



Reset

Confidence Signal

Every




Pump



Alarm Indicators




Gas Alarm Acknowledge




Fault Alarms

Calibration Overdue




Service Required





Failed Sensor





Zero Fault



Flow Fault



Battery Life



Charging

